

Kenwood TS-2000

RX sensitivity on medium wave

AM BC-stations on medium wave is poorly received as delivered from factory. There is however a very quick and easy way to fix this. No soldering skills required(!) only a Phillips screwdriver, that's all.

1. Remove the bottom cover
2. Locate the plastic mini-jumper labeled "Local/DX" close to the antenna connector
3. Move the jumper from "Local" to the "DX" position
4. Replace the bottom cover.

Done!